

---

<b>Addendum Number</b>	4
Addendum Date of Issue	February 01, 2019
RFVQ Number	18163 (RFQ 19009)
RFVQ Description	Sprinkler Replacement Services(Roster Refresh and RFQ 19009 for 10,30,40 Gordonridge Place, Toronto)
Page(s):	1
Attachment(s):	0

---

This Addendum forms part of the above mentioned RFVQ document and is to be read, interpreted, and coordinated with all other parts. The following revisions supersede the information contained in the original RFVQ documents issued for the above-named project to the extent referenced and shall become part thereof.

The following information supplements and/or supersedes the RFVQ document issued on **January 10, 2019**.

#### **1. SUBMISSION DEADLINE**

The Submission Deadline has changed to **February 8, 2019**. The closing time remains the same at 2:00:00 p.m. Toronto time.

#### **2. QUESTIONS AND ANSWERS**

Q1: The emergency panel at 40 Gordonridge does not have room to add the compressor. Please advise.  
**A1: The Contractor shall allow for installing a sub-panel to the existing emergency panel to accommodate the compressor. The Contractor coordinate with TCHC the location of the new sub panel and any shutdown of equipment.**

All other terms and conditions remain the same.



Shams Umarov  
Sourcing Manager, Strategic Procurement  
Toronto Community Housing